CONSTRUCTION PERFORMANCE GUIDE & LIMITED WARRANTY

BY



515-986-3900 OFFICE 515-986-0050 FAX www.firstcalliowa.com

TO:

Issued to the contracted Property Owner of a specific property and scope of work specified in the contract documents.

BUILDER'S LIMITED WARRANTY

SECTION #1

IDENTITY OF WARRANTOR

FIRSTCALL, Inc. D.B.A. FIRSTCALL Remodeling, Inc., FIRSTCALL Restoration, Inc. & FIRSTCALL Exteriors, Inc. located at 3910 SE Capitol Circle, Grimes, Iowa 50111.

TO WHOM GIVEN

This limited warranty is extended to you as the owner of the Home remodeled or repaired by FIRSTCALL, Inc.

COVERAGE TERM

The Limited Warranty commences on the date the construction is substantially completed. This Limited Warranty terminates five (5) years after its commencement.

LIMITED WARRANTY COVERAGE

The Builder warrants that for five (5) years, beginning on the Limited Warranty Coverage Term date, the effected remodeled areas will be free from defects due to noncompliance with the Performance Standards attached to and incorporated into this Limited Warranty.

CONSEQUENTIAL DAMAGES

Consequential damages are not covered by this Limited Warranty.

REMEDY

If a defect occurs in an item which is covered by this Limited Warranty, the Builder will repair, replace, or pay the Homeowner the reasonable cost of repairing or replacing the defective item(s).

EXCLUSIONS

This Limited Warranty shall not extend to or include of be applicable to:

- A. Defects in outbuildings including, but not limited to detached garages and detached carports (except outbuildings which contain the plumbing, electrical, heating, cooling or ventilation systems serving the Home); site located swimming pools and other recreational facilities; driveways; walkways; patios; boundary walls; retaining walls; fences; landscaping (including sodding, seeding, shrubs, trees and plantings); off-site improvements not a part of the Home itself;
- B. Concrete flatwork; floors of basements, driveways, sidewalks, patios, concrete floors of attached garages that are built separately from foundation walls or any concrete used in a non foundation way. (Concrete flatwork is prone to cracking due to weather changes, sub soil conditions, and or its specific use.)
- C. Measures will be taken to protect driveways during construction however, driveways damaged by vehicles necessary for the construction process such as dumpsters, cranes, delivery vehicles, and possible staining of the surface due to dumpster leakage etc. is not covered under this warranty.
- D. Loss or damage to real property which is not part of the Home covered by this Limited Warranty may not be included in the original purchase price of the Home as stated on the Certificate;
- E. Any damage to the extent it is caused or made worse by:
 - 1. Negligence, improper maintenance or improper operation by anyone other than the Builder, its employees, agents or subcontractors; or
 - 2. Failure by the Homeowner or by anyone other than the Builder, its employees, agents or subcontractors to comply with the warranty requirements of manufactures of appliances, fixtures and items of equipment; or
 - 3. Failure by the Homeowner to give notice to the Builder of any defects within a reasonable time; or
 - 4. Changes of the grading of the ground by anyone other than the Builder, its employees, agents or subcontractors; or
 - 5. Changes, alterations or additions made to the Home by anyone after the Homeowner take possession; or

- 6. Dampness or condensation due to the failure of the Homeowner to maintain adequate ventilation;
- F. Loss or damage which the Homeowner has not taken timely action to minimize;
- G. Any defect in, caused by, or resulting from materials or work supplied by anyone other than the Builder, its employees, agents, or subcontractors;
- H. Normal wear and tear or normal deterioration;
- I. Loss or damage, not otherwise excluded under this Limited Warranty, which does not constitute a defect in the construction of the Home by the Builder, its employees, agents or subcontractors;
- J. Loss or damage caused by or resulting from accidents, riot and civil commotion, fire, explosion, smoke, water escape, falling objects, aircraft, vehicles, Acts of God, lightning, windstorm, hail, flood, mud slide, earthquake, volcanic eruption, wind-driven water and changes in the underground water table which were not reasonably foreseeable;
- K. Loss or damage caused by or resulting from seepage of water;
- L. Insect damage;
- M. Loss or damage which arises while the Home is being used primarily for nonresidential purposes;
- N. Bodily injury or damage to personal property;
- O. Failure of Owner to pay Contractor in full for the entire contracted amount;
- P. Loss or damage caused by or resulting from abnormal loading on floors by the Homeowner which exceeds design loads as mandated by codes;
- Q. Plumbing labor on fixtures not provided by the plumbing contractor;
- R. Costs of shelter, transportation, food, moving, storage, or other incidental expenses related to inconvenience or relocation during repairs; and
- S. Consequential damages.

WARRANTY SERVICE

REQUEST FOR WARRANTY SERVICE

The Homeowner with a warranty request should first send a clear and specific written request to the Builder at the address provided.

DEFINITIONS

Except as otherwise provided, the terms used in this Limited Warranty shall have the meanings assigned below:

- **A.** "Appliances, Fixtures and Items Or Equipment"- Include but is not limited to: furnaces, boilers, oil tanks and fittings, air purifiers, air handling equipment, ventilating fans, air conditioning equipment, water heaters, pumps, stoves, refrigerators, garbage disposers, compactors, dishwashers, automatic door openers, washers and dryers, bathtubs, sinks, toilets, faucets, lighting fixtures, and circuit breakers.
- B. "Builder" Des Moines Design & Remodeling Company a division of Scott Cierzan Custom Builders, Inc.
- C. **"Home"** A single family house, or a Unit in a for sale multi-unit residential building of four (4) units or less which title to the individual units is transferred to owners under a condominium or cooperative regime.
- D. "Homeowner" The first person to whom the Home is sold by the Builder and his successors in title. Homeowner does not include the Builder or any firm under common control of the Builder.
- E. "Major Structural Defect" Actual physical damage to any of the load-bearing portions of the Home caused by failure of such load-bearing portions which affects their load-bearing functions to the extent that the Home becomes unsafe, unsanitary or otherwise unlivable.
- F. "Performance Standards" The locally applicable building codes, locally accepted building practices and performance standards which describe the Builder's obligation for specific defects under the Limited Warranty.
- G. "Systems" Exclusive of appliances, fixtures and items of equipment, include the following:
 - 1. "Plumbing System" Gas supply lines and fittings; water supply, waste and vent peoples and their fittings; septic tanks and their drain field; water, gas and sewer services piping and their extensions to the tie-in of public utility connection, or on-site well and sewage disposal system.
 - 2. "Electrical System" All wiring, electrical boxes, switches, outlets and connections up to the public utility connections.
 - 3. "Heating, Cooling and Ventilation Systems" All ductwork, steam, water and refrigerant lines, registers, connector, radiation elements and dampers.
- H. The term "substantial completion" is defined as: the point at which the space can be occupied for the purpose for which it was built or remodeled.

OTHER CONDITIONS

All material and equipment will follow the manufacturer's warranty. If the manufacturer's warranty for equipment exceeds the Contractor's labor warranty, the Owner may be responsible for the cost to reinstall defective equipment.

Independence from the Contract of Sale. This Limited Warranty is independent of the contract between the Homeowner and the Builder for the construction of the Home and/or its sale to the Homeowner. Contract disputes which are not Limited Warranty disputes are not eligible for informal dispute settlement under this Limited Warranty. Nothing contained in the construction and/or sale contract or any other contract between the Homeowner and the Builder can restrict or override the provisions of this Limited Warranty. The Homeowner and the Builder may contract for additional standards or requirements, but such agreement between the Homeowner and the Builder must be agreed upon in writing.

Notice. All notices to the Builder or the Homeowner must be sent by mail.

SECTION #2

PERFORMANCE STANDARDS

INTRODUCTION

The following is intended to acquaint you with the responsibilities of the Builder under this Limited Warranty. If a defect that results in actual physical damage to the Home occurs, the Performance Standards will be used to determine the Builder's obligation under this Limited Warranty. If a specific defect is not addressed in the Performance Standards, one of the following standards will be used to determine the Builder's obligation under this Limited Warranty: (a) Locally adopted codes; or (b) Model codes covering building, mechanical, plumbing and electrical systems; or (c) Codes of nearby jurisdictions; or (d) Locally accepted building practices.

HOMEOWNER RESPONSIBILITIES

The Home requires an active maintenance effort on the Homeowner's part to reduce the likelihood of damage due to neglect, improper maintenance, or abnormal use. NOTE: Damage caused or made worse by Homeowner negligence, improper maintenance, or improper operation is expressly excluded under this Builder's Limited Warranty.

PERFORMANCE STANDARDS

The Performance Standards list specific items (defects) within each separate area of coverage. The standards are expressed in terms of performance criteria. For easy comprehension, the format is designed as follows:

- 1. Possible Deficiency a brief statement, in simple terms, of problems that may be encountered.
- 2. Performance Standard a performance standard relating to a specific deficiency.
- 3. Responsibility a statement of the corrective action required of the Builder to repair the deficiency or a statement of the Homeowner's maintenance responsibilities.

1. SITE WORK

A. Site Grading

Possible Deficiency Settling of ground around foundation, utility trenches, or other areas.

Performance Standard Settling of ground around foundation and other filled areas shall not interfere with

water drainage away from the home.

Responsibility If the Builder has provided final grading, the Builder shall fill settled areas

affecting proper drainage, one time only, during the Limited Warranty period. The Homeowner shall be responsible for removal and replacement of shrubs and other

landscaping in affected areas.

B. Site Drainage

Possible Deficiency Improper drainage of site.

Performance Standard The necessary grades and swales shall have been established by the Builder to

insure proper drainage away from the Home. Standing or ponding water shall not remain for extended periods in the immediate area after a rain (generally no more than 24 hours). The possibility of standing water after an unusually heavy rainfall should be anticipated. No grading determination shall be made while there is frost

or snow on the ground, or while ground is saturated.

Responsibility The Builder is responsible only for initially establishing the proper grades and

swales. The Homeowner is responsible for maintaining such grades and swales

once they have been properly established.

2. CONCRETE

A. Expansion Joints

Possible Deficiency Separation or movement of concrete slabs within the structure at expansion joints.

Performance Standard Concrete slabs within the structure are designed to move at expansion joints.

Responsibility None.

B. Cast- In - Place Concrete

(1) **Possible Deficiency** Basement or foundation wall cracks.

Performance Standard Shrinkage cracks are not unusual in concrete foundation walls. Such cracks greater

than 1/8 inch in width shall be repaired.

Responsibility Builder will repair cracks in excess of 1/8 inch width.

(2) Possible Deficiency Cracking of basement floor.

Performance Standard Minor cracks in concrete basement floors are normal. Cracks exceeding 3/16 inch

in width or 1/8 inch in vertical displacement shall be repaired.

Responsibility Builder will repair cracks exceeding maximum tolerances by surface

patching or other methods as required.

(3) **Possible Deficiency** Cracking of slab in attached garage.

Performance Standards Cracks in garage slabs in excess of 1/4 inch in width or 1/4 inch in vertical

displacement shall be repaired.

Responsibility Builder will repair cracks that exceed maximum tolerances by surface

patching or other methods as required.

(4) **Possible Deficiency** Settling, heaving, or separating of stoops, steps or garage floors.

Performance Standards Stoops, steps, or garage floors shall not settle, heave, or separate in excess

of 3/4 inch from the house structures.

Responsibility Builder will take whatever corrective action is required to meet the

Performance Standard.

3. MASONRY

A. Unit Masonry

Deficiency Possible Cracks in masonry wall or veneer.

Performance Standard Small hairline cracks due to shrinkage are common in mortar joints in

masonry construction. Cracks greater than 1/4 inch in width are

considered excessive.

Responsibility Builder will repair cracks in excess of Performance Standards by pointing

or patching. Builder will not be responsible for color variation between

old and new mortar.

4. WOOD AND PLASTIC

A. Rough Carpentry

(1) **Possible Deficiency** Floors squeak or sub floor appears loose.

Performance Standard Floor squeaks and loose sub floor are often temporary conditions common

to new construction, and a squeak-proof floor cannot be guaranteed.

Responsibility Builder will correct the problem only if caused by an underlying

construction defect.

(2) Possible Deficiency Bowed walls.

Performance Standard All interior and exterior walls have slight variances on their finished

surfaces. Bowing of walls should not detract from or blemish the wall's finished surface. Walls should not bow more than 1/4 inch out of line

within any 32 inch horizontal or vertical measurement.

Responsibility Builder will repair to meet Performance Standard.

(3) **Possible Deficiency** Out-of plumb walls.

Performance Standard Walls should not be more than 1/4 inch out of plumb for any 32 inch

vertical measurement.

Responsibility Builder will repair to meet the Performance Standard.

B. Finish Carpentry (Interior)

Possible Deficiency Sub-standard work of interior trim workmanship.

Performance Standard Joints in moldings or joint between moldings and adjacent surface shall

not result in open joints exceeding 1/16 inch in width.

Responsibility Builder will repair defective joints, as defined. Caulking is acceptable.

C. Finish Carpentry (Exterior)

Possible Deficiency Poor quality of exterior trim workmanship.

Performance Standard Joints between exterior trim elements, including siding and masonry, shall

not result in open joints in excess of 1/4 inch.

Responsibility Builder will repair open joints, as defined. Caulking is acceptable.

5. THERMAL AND MOISTURE PROTECTION

A. Waterproofing

Possible Deficiency Leaks in basement.

Performance Standard Leaks resulting in actual trickling of water shall be repaired. Leaks

caused by improper landscaping or failure to maintain proper grades are not covered by this Limited Warranty. Dampness of the walls or floors may occur in new construction and is not considered a deficiency.

Responsibility Builder will take such action as necessary to correct basement leaks

except where the cause is determined from Homeowner action or

negligence.

B. Insulation

Possible Deficiency Insufficient insulation.

Performance Standard Insulation shall be installed in accordance with applicable energy and

building code requirements.

Responsibility Builder will install insulation in sufficient amounts to meet Performance

Standards.

C. Louvers and Vents

Possible Deficiency Leaks due to snow or rain driven into the attic through louvers or vents.

Performance Standard Attic vents and/or louvers must be provided for proper ventilation of the

attic space of the structure.

Responsibility None.

D. Roofing and Siding

(1) **Possible Deficiency** Ice build-up on roof.

Performance Standard During prolonged cold spells, ice build-up is likely to occur at the eaves

of a roof. This condition occurs when snow and ice accumulate and

gutters and downspouts freeze up.

Responsibility Prevention of ice build-up is a Homeowner maintenance item.

(2) **Possible Deficiency** Roof or Flashing leaks.

Performance Standard Roof or Flashing shall not leak under normally anticipated conditions.

Responsibility Builder will repair any verified roof or flashing leak.

E. Sheet Metal

(1) Possible Deficiency Gutters and/or downspouts leak.

Performance Standard Gutters and downspouts shall not leak but gutters may overflow during

heavy rain.

Responsibility Builder will repair leaks. It is a Homeowner responsibility to keep

gutters and downspouts free of leaves and debris which could cause

overflow.

(2) **Possible Deficiency** Water standing in gutters.

Performance Standard When gutter is unobstructed by debris, the water level shall not exceed

one (1) inch in depth. Industry practice is to install gutters approximately level. Consequently, it is entirely possible that small amounts of water

will stand in certain sections of gutter immediately after a rain.

Responsibility Builder will correct to meet Performance Standard.

F. Sealants

Possible Deficiency Leaks in exterior walls due to inadequate caulking.

Performance Standard Joints and cracks in exterior wall shall be properly caulked to exclude the

entry of water.

Responsibility Builder will repair/or caulk joints in exterior wall as required by

Performance Standard.

6. DOORS AND WINDOWS

A. Wood and Plastic Doors(1) Possible Deficiency

Possible Deficiency Warpage of exterior doors.

Performance Standard Exterior doors will warp to some degree due to temperature differential on

inside and outside surfaces. However, they shall not warp to the extent that they become inoperable or cease to be weather resistant or exceed National Woodwork Manufacturers Association Standards (1/4 inch,

measured diagonally from corner to corner).

Responsibility Builder will correct or replace and refinish defective doors, during the

Limited Warranty period.

(2) **Possible Deficiency** Warpage of interior passage doors.

Performance Standard Same standard as exterior doors.

Responsibility Builder will correct or replace and refinish defective doors to match

existing doors as nearly as possible.

B. Glass

Possible Deficiency Broken glass.

Performance Standard None.

Responsibility Broken glass not reported to the Builder prior to closing is the

Homeowner's responsibility.

C. Garage Doors

(1) **Possible Deficiency** Garage doors fail to operate properly, under normal use.

Performance Standard Garage doors shall operate properly.

Responsibility Builder will correct or adjust garage doors as required.

(2) Possible Deficiency Garage doors allow entrance of snow or water.

Performance Standard Garage doors shall be installed as recommended by the manufacturer.

Some entrance of elements con be expected.

Responsibility Builder will adjust or correct garage doors to meet manufacturer's

recommendations.

D. Wood Plastic and Metal Windows

(1) Possible Deficiency Malfunction of windows.

Performance Standard Windows shall operate with reasonable ease, as designed.

Responsibility Builder will correct or repair as needed.

(2) **Possible Deficiency** Condensation and/or frost on windows.

Performance Standard Windows will collect condensation on interior surfaces when extreme

temperature differences and high humidity levels are present. Condensation is usually the result of climatic/humidity conditions.

Responsibility Unless directly attributed to faulty installation, window condensation is a

result of conditions beyond the Builder's control. No corrective action is

required.

E. Weather-stripping and Seals

Possible Deficiency Air infiltration around doors and windows.

Performance Standard Some minor infiltration is normally noticeable around doors and

windows, especially during high winds. Poorly fitted weather-stripping

shall be adjusted or replaced.

Responsibility Builder will adjust or correct poorly fitted doors, windows and poorly

fitted weather-stripping.

7. FINISHES

A. Gypsum Wallboard

Possible Deficiency Defects which appear during first year of the Limited Warranty such as

nail pops, blisters in tape, or other blemishes.

Performance Standard Slight "imperfections" such as nail pops, seam lines and cracks not

exceeding 1/16 inch in width are common in gypsum wallboard

installations and are considered acceptable.

Responsibility Builder will repair cracks one time only, during the Limited Warranty

period.

B. Ceramic Tile

(1) **Possible Deficiency** Ceramic tile cracks or becomes loose.

Performance Standard Ceramic tile shall not crack or become loose.

Responsibility Builder will replace cracked tiles and re-secure loose tiles unless the

defects were caused by the Homeowner action or negligence. Builder will not be responsible for discontinued patterns or color variations in ceramic

tile.

(2) Possible Deficiency Cracks appear in grouting of ceramic tile joints or at junctions with other

materials such as a bathtub.

Performance Standard Cracks in grouting of ceramic tile joints are commonly due to normal

shrinkage conditions.

Responsibility Builder will repair grouting if necessary one time only, during the Limited

Warranty period. Builder will not be responsible for color variations or

discontinued colored grout.

C. Finished Wood Flooring

Possible Deficiency Cracks developing between floor boards.

Performance Standard Cracks in excess of 1/8 inch in width shall be corrected.

Responsibility Builder will repair cracks in excess of 1/8 inch within the first year of the

Limited Warranty period, by filling or replacing, at Builder's option.

D. Resilient Flooring

(1) **Possible Deficiency** Nail pops appear on the surface of resilient flooring.

Performance Standard Readily apparent nail pops shall be repaired.

Responsibility Builder will correct nail pops which have broken the surface. Builder will

repair or replace, at Builder's sole option, resilient floor covering in the affected area with similar material. Builder will not be responsible for

discontinued patterns or color variations in the floor covering.

(2) Possible Deficiency Depressions or ridges appear in the resilient flooring due to sub floor

irregularities.

Performance Standard Readily apparent depressions or ridges exceeding 1/8 inch shall be

repaired. The ridge or depression measurement is taken as the gap created at one end of a six-inch straightedge placed over the depression or ridge with three inches of the straightedge on one side of the defect, held tightly

to the floor.

Responsibility Builder will take corrective action as necessary, to bring the defect within

acceptable tolerance so that the affected area is not readily visible. Builder will not be responsible for discontinued patterns or color

variations in floor covering.

E. Painting

(1) Possible Deficiency Painting required as corollary repair because of other work.

Performance Standard Repairs required under this Limited Warranty shall be finished to match

surrounding areas as closely as practicable.

Responsibility Builder will finish repair areas as indicated.

(2) **Possible Deficiency** Mildew or fungus on painted surfaces.

Performance Standard Mildew or fungus will form on a painted surface if the structure is subject

to abnormal exposures (i.e., rainfall, ocean, lake or river front).

Responsibility Mildew or fungus formation is a condition the Builder cannot control and

is a Homeowner maintenance item unless it its a result of noncompliance

with other sections of the Performance Standard.

F. Wall Covering

Possible Deficiency Peeling of wall covering.

Performance Standard Peeling of wall covering shall not occur.

Responsibility Builder will repair or replace defective wall covering applications.

G. Carpeting

(1) **Possible Deficiency** Open carpet seams.

Performance Standard Carpet seams will show. However, no visible gap is acceptable.

Responsibility Builder will correct.

(2) Possible Deficiency Carpeting becomes loose, seams separate or stretching occurs.

Performance Standard Wall to wall carpeting, installed as the primary floor covering, when

stretched and secured properly, shall not come up, become loose, or

separate from its point of attachment.

Responsibility Builder will re-stretch or re-secure carpeting as needed, if original

installation was performed by Builder.

(3) Possible Deficiency Spots on carpet, minor fading.

Performance Standard Exposure to light may cause spots on carpet and/or minor fading.

Responsibility None.

8. SPECIALTIES

A. Fireplaces

(1) **Possible Deficiency** Fireplace or chimney does not draw properly.

Performance Standard A properly designed and constructed fireplace and chimney shall function

properly. It is normal to expect that high winds can cause temporary negative draft situations. Similar negative draft situations can also be caused by obstructions such as large branches of trees too close to the chimney. Some homes may need to have a window opened slightly to create an effective draft if they have been insulated and weatherproofed to

meet high energy conservation criteria.

Responsibility Builder will determine the cause of malfunction and correct, if the

problem is one of design construction of the fireplace.

(2) Possible Deficiency Firebox paint changed by fire.

Performance Standard None.

Responsibility None. Heat from fires will alter finish.

(3) Possible Deficiency Cracked firebrick and mortar joints.

Performance Standard None.

Responsibility None. Heat and flames from "roaring" fires will cause cracking.

9. EQUIPMENT

A. Residential Equipment

(1) Possible Deficiency Surface cracks, joint delaminations and chips in high pressure laminates

on vanity and kitchen cabinet countertops.

Performance Standard Countertops fabricated with high pressure laminate coverings shall not

delaminate.

Responsibility Builder will replace delaminated coverings to meet specified criteria.

Builder will not be responsible for chips and cracks noted following first

occupancy.

(2) **Possible Deficiency** Kitchen cabinet malfunctions.

Performance Standard Warpage not to exceed 1/4 inch as measured from face frame to point of

furthermost warpage with door or drawer front in closed position.

Responsibility Builder will correct or replace doors or drawer fronts.

10. PLUMBING

A. Water Supply System

Possible Deficiency Plumbing pipes freeze and burst.

Performance Standard Drain, waste and vent, and water pipes shall be adequately protected, as

required by applicable code, during normally anticipated cold weather, and as defined in accordance with ASHRAE design temperatures, to

prevent freezing.

Responsibility Builder will correct situations not meeting the code. It is the

Homeowner's responsibility to drain or otherwise protect lines and

exterior faucets exposed to freezing temperatures.

B. Plumbing System

(1) Possible Deficiency Faucet or valve leak.

Performance Standard No valve or faucet shall leak due to defects in workmanship and materials.

Responsibility Builder will repair or replace the leaking faucet or valve.

(2) Possible Deficiency Defective plumbing fixtures, appliances, or trim fittings.

Performance Standard Fixtures, appliances, or fittings shall comply with their manufacturer's

standards.

Responsibility Builder will replace any defective fixture or fitting which does not meet

acceptable standards, as defined by the manufacturer.

(3) Possible Deficiency Noisy water pipes.

Performance Standard There will be some noise emitting from the water pipe system, due to the

flow of water. However, water hammer shall be eliminated.

Responsibility Builder cannot remove all noises due to water flow and pipe expansion.

Builder will correct to eliminate "water hammer."

(4) **Possible Deficiency** Leakage from any piping.

Performance Standard No leaks of any kind shall exist in any soil, waste, vent, or water pipe.

Condensation on piping does not constitute leakage, and is not covered.

Responsibility Builder will make repairs to eliminate leakage.

(5) **Possible Deficiency** Stopped up sewers, fixtures, and drains.

Performance Standard Sewers, fixtures, and drains shall operate properly.

Responsibility Builder will not be responsible for sewers, fixtures, and drains which are

clogged through the Homeowner negligence. If a problem occurs, the Homeowner should consult Builder for a proper course of action. Where defective construction is shown to be the cause, the Builder will assume the cost of the repair; where Homeowner negligence is shown to be the

cause, the Homeowner shall assume all repair costs.

11. HEATING AND COOLING

A. Heating

(1) **Possible Deficiency** Inadequate heating.

Performance Standard Heating system shall be capable of producing an inside temperature of 70

degrees F, as measured in the center of each room at a height of 5 feet above the floor, under local outdoor winter design conditions as specified in ASHRAE handbook. Federal, state or local energy codes shall supersede this standard where such codes have been locally adopted.

Responsibility Builder will correct heating system to provide the required temperatures.

However, the Homeowner shall be responsible for balancing dampers,

registers, and other minor adjustments.

B. Cooling

(1) Possible Deficiency Inadequate cooling.

Performance Standard Where air-conditioning is provided, the cooling system shall be capable of

maintaining a temperature of 78 degrees F, as measured in the center of each room at a height of 5 feet above the floor, under local outdoor summer design conditions as specified in ASHRAE handbook. In the case of outside temperatures exceeding 95 degrees F, a differential of 15

degrees F from the outside temperature will be maintained. Federal, state, or local energy codes shall supersede this standard where such codes have

been locally adopted.

Responsibility Builder will correct cooling system to meet temperature conditions, in

accordance with specifications.

C. Evaporative Cooling

(1) Possible Deficiency Improper mechanical operation.

Performance Standard Equipment shall function properly at temperature standard set.

Responsibility Builder will correct and adjust so that blower and water system operate as

designed.

12. VENTILATION

A. Air Distribution

Possible Deficiency Noisy ductwork.

Performance Standard When metal is heated it expands and when cooled it contracts. The result

is "ticking" or "crackling" which is generally to be expected.

Responsibility None.

13. ELECTRICAL

A. Electrical Conductors, Fuses, and Circuit Breakers

Possible Deficiency Fuses blow or circuit breakers (excluding ground fault interrupters) "kick

out."

Performance Standard Fuses and circuit breakers shall not activate under normal usage.

Responsibility Builder will check wiring circuits for conformity with local, state, or

approved national electrical code requirements. Builder will correct

circuitry not conforming to code specifications.

B. Outlets, Switches, and Fixtures

(1) **Possible Deficiency** Drafts from electrical outlets.

Performance Standard Electrical junction boxes on exterior walls may produce air flow whereby

the cold air can be drawn through the outlet into a room. The problem is

normal in new home construction.

Responsibility None.

(2) Possible Deficiency Malfunction of electrical outlets, switches, or fixtures.

Performance Standard All switches, fixtures, and outlets shall operate as intended.

Responsibility Builder will repair or replace defective switches, fixtures, and outlets.

C. Service and Distribution

Possible Deficiency Ground fault interrupter (GFI) trips frequently.

Performance Standard Ground fault interrupters are sensitive safety devices installed into the

electrical system to provide protection against electrical shock. These

sensitive devices can be tripped very easily.

Responsibility Builder shall install ground fault interrupter in accordance with approved

electrical code. Tripping is to be expected and is not covered, unless due

to a construction defect.

D. Wiring

Possible Deficiency Failure of wiring to carry its designed load.

Performance Standard Wiring should be capable of carrying the designed load for normal

residential use.

Responsibility Builder will check wiring for conformity with local, state, or approved

national electrical code requirements. Builder will repair wiring not

conforming to code specifications.